

FIG. 1A

100




FIG. 1B




FIG. 1C




FIG. 1D




FIG. 2A




FIG. 2B

202120-1015/001




FIG. 3




FIG. 4




FIG. 5




FIG. 6

700




FIG. 7



# Impact of a Mode Stripper [6umX80um] on a Butterfly MMI Split Ratio




FIG. 8